

Water / Building & Grounds Report
August 2025

Worked on installing 24" contact main at Well 1

Put out Lead and Copper bottles

Did yearly samples

Installed new electrical shut off in well 1

I moved paver for highway and I ran roller for them

Windshield shattered on backhoe

Went to 5 star and got a new one

Took truck 1 to BW no brakes